

Unsold Lots - Stock and Equipment of Kitchen Manufacturer

Lot No	Description
2	Holzma HPL 11/43/22 Beam saw (1997)Machine Number: 0-240-01-0232Year of Manufacture: 1997Additional Information:With automated roller infeed, pallet lifter, controls, fencing and light guardsPlease Note:RAMS: A work Method Statement and Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Machine is not under power
4	Giben Smart SP90 Beam saw (2004)Machine Number: 909760Year of Manufacture: 2004Additional Information:Approx 3750mm with HMIPlease Note:RAMS: A work Method Statement and Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Machine is not under power
5	Giben Smart SP90 Beam saw (2004)Machine Number: 909696Year of Manufacture: 2004Additional Information:Approx 3750mm with HMI, one table missingPlease Note:RAMS: A work Method Statement and Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Machine is not under power
6	Giben Smart SP90 Beam saw (2004)Machine Number: 909761Year of Manufacture: 2004Additional Information:Approx 3750mm with HMIPlease Note:RAMS: A work Method Statement and Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Machine is not under power
7	Giben Fastmatic Beam saw (1996)Machine Number: MCL.96138Year of Manufacture: 1996Additional Information:Approx 3250mm with HMIPlease Note:RAMS: A work Method Statement and Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Machine is not under power
8	Kuper SF Scheer FM14 Single beam saw Machine Number: 2020527Additional Information:with SM19.34.1 controlsPlease Note:RAMS: A work Method Statement and Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Machine is not under power
9	Bargstedt TBK22/D/25/10 Double sided feeder unit (2000)Machine Number: 0-280-03-3925Year of Manufacture: 2000Additional Information:Belt width approx 950mmPlease Note:RAMS: A work Method Statement and Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Machine is not under power
10	Bargstedt TSK15/D/25/10 Double sided stacker unit (2000)Machine Number: 0-281-03-3926Year of Manufacture: 2000Please Note:RAMS: A work Method Statement and Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Machine is not under power
11	Homag Profiline KF20/13/QA/25 Automatic double edge bander (2020)Machine Number: 0-202-03-8013Year of Manufacture: 2020Additional Information:With Homag Homatic NC21 controlsPlease Note:RAMS: A work Method Statement and Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Machine is not under power
15	V.Alberti Syncro-CN CNC Drilling Machine (2005)Machine Number: 12060Year of Manufacture: 2005Additional Information:With off-station controls, roller infeed & outfeed and fencing, approx 800mm conveyor widthPlease Note:RAMS: A work Method Statement and Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Machine is not under power
20	Blum BoxPress ZMM 6300 3SBP Box press (2004)Machine Number: AA00245Year of Manufacture: 2004Additional Information:Dimensions - 650mm x 1200mm x 200mmPlease Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Machine is not under power
21	Blum BoxPress ZMM 6300 12BP Box press (2005)Machine Number: AA00280Year of Manufacture: 2005Additional Information:Dimensions - 650mm x 1200mm x 200mmPlease Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Machine is not under power
22	Blum BoxPress ZMM 6300 12BP Box press (2003)Machine Number: AA00225Year of Manufacture: 2003Additional Information:Dimensions - 650mm x 1200mm x 200mmPlease Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Machine is not under power
23	Blum BoxPress ZMM 6300 12BP Box press (2005)Machine Number: AA00281Year of Manufacture: 2005Additional Information:Dimensions - 650mm x 1200mm x 200mmPlease Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Machine is not under power
24	Comil CF2000 Electronic through-feed carcass press Machine Number: 830701500Additional Information:Dimensions - 3600mm x 600mm x 1500mm, with Xilla controlsPlease Note:RAMS: A work Method Statement and Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Machine is not under power
25	Comil CF2001 Electronic through-feed carcass press Machine Number: 29570Additional Information:Dimensions - 3600mm x 600mm x 1500mm, with Fiessler Elektronik light safety barrierPlease Note:RAMS: A work Method Statement and Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Machine is not under power
26	Comil CF2002 Electronic through-feed carcass press Additional Information:Dimensions - 3600mm x 600mm x 1500mm, with Slingsby roller infeed (belt width approx. 620mm)Please Note:RAMS: A work Method Statement and Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Machine is not under power

27	Comil CF2003 Electronic through-feed carcass press Machine Number: 166/87Additional Information:Dimensions - 3600mm x 600mm x 1500mm, with roller infeed (belt width approx. 620mm)Please Note:RAMS: A work Method Statement and Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Machine is not under power
49	SDC Tri Axle sign written box body trailer (2010)Year of Manufacture: 2010Additional Information:with Dhollandia tail liftPlease Note:LOLER: This lot has no record of Thorough Examination. The purchaser must ensure a Thorough Examination is carried out by a competent person prior to first use. The purchaser will be required to sign an undertaking confirming their agreement.Lot Specific Clearance Arrangements:This lot must be collected between Monday 9th - Wednesday 11th September 2024.
50	Cartwright 25ft swap-body GRP box unit Additional Information:Aluminium frame with roller doorPlease Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Lot Specific Clearance Arrangements:This lot must be collected between Monday 9th - Wednesday 11th September 2024.
51	25ft swap-body GRP box unit Additional Information:Aluminium frame with barn doorsPlease Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Lot Specific Clearance Arrangements:This lot must be collected between Monday 9th - Wednesday 11th September 2024.
55	25ft swap-body GRP box unit Additional Information:Aluminium frame with barn doorsPlease Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Lot Specific Clearance Arrangements:This lot must be collected between Monday 9th - Wednesday 11th September 2024.
56	25ft swap-body GRP box unit Additional Information:Aluminium frame with barn doorsPlease Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Lot Specific Clearance Arrangements:This lot must be collected between Monday 9th - Wednesday 11th September 2024.
57	25ft swap-body GRP box unit Additional Information:Aluminium frame with roller doorPlease Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Lot Specific Clearance Arrangements:This lot must be collected between Monday 9th - Wednesday 11th September 2024.
58	25ft swap-body GRP box unit Additional Information:Aluminium frame with barn doorsPlease Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Lot Specific Clearance Arrangements:This lot must be collected between Monday 9th - Wednesday 11th September 2024.
59	25ft swap-body GRP box unit Additional Information:Aluminium frame with barn doorsPlease Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Lot Specific Clearance Arrangements:This lot must be collected between Monday 9th - Wednesday 11th September 2024.
60	25ft swap-body GRP box unit Additional Information:Aluminium frame with barn doorsPlease Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Lot Specific Clearance Arrangements:This lot must be collected between Monday 9th - Wednesday 11th September 2024.
61	25ft swap-body GRP box unit Additional Information:Aluminium frame with barn doorsPlease Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Lot Specific Clearance Arrangements:This lot must be collected between Monday 9th - Wednesday 11th September 2024.
62	25ft swap-body GRP box unit Additional Information:Aluminium frame with barn doorsPlease Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Lot Specific Clearance Arrangements:This lot must be collected between Monday 9th - Wednesday 11th September 2024.
63	25ft swap-body GRP box unit Additional Information:Aluminium frame with barn doorsPlease Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Lot Specific Clearance Arrangements:This lot must be collected between Monday 9th - Wednesday 11th September 2024.
64	25ft swap-body GRP box unit Additional Information:Aluminium frame with barn doorsPlease Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Lot Specific Clearance Arrangements:This lot must be collected between Monday 9th - Wednesday 11th September 2024.
65	25ft swap-body GRP box unit Additional Information:Aluminium frame with barn doorsPlease Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Lot Specific Clearance Arrangements:This lot must be collected between Monday 9th - Wednesday 11th September 2024.
66	25ft swap-body GRP box unit Additional Information:Aluminium frame with barn doorsPlease Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Lot Specific Clearance Arrangements:This lot must be collected between Monday 9th - Wednesday 11th September 2024.
67	25ft swap-body GRP box unit Additional Information:Aluminium frame with barn doorsPlease Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Lot Specific Clearance Arrangements:This lot must be collected between Monday 9th - Wednesday 11th September 2024.

68	25ft swap-body GRP box unit Additional Information:Aluminium frame with barn doorsPlease Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Lot Specific Clearance Arrangements:This lot must be collected between Monday 9th - Wednesday 11th September 2024.
73	32ft X 12ft security cabin Please Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.
80	2 x 8 tier mobile shelving units
82	9 x Various four section mobile stock trolleys Additional Information:Styles and sizes may vary slightly Please Note:Viewing is recommended to satisfy yourself that this particular lot fits your requirements.
83	10 x Various four section mobile stock trolleys Additional Information:Styles and sizes may vary slightly Please Note:Viewing is recommended to satisfy yourself that this particular lot fits your requirements.
84	10 x Various four section mobile stock trolleys Additional Information:Styles and sizes may vary slightly Please Note:Viewing is recommended to satisfy yourself that this particular lot fits your requirements.
85	10 x Various four section mobile stock trolleys Additional Information:Styles and sizes may vary slightly Please Note:Viewing is recommended to satisfy yourself that this particular lot fits your requirements.
88	Steel fabricated smoking shelter Additional Information:Dimensions approx. - 4.5m x 5m
90	20 x Bays of Dexion boltless pallet racking Additional Information:comprising: 22 x end frames (7.5m), 90 x pairs various crossbeams (2.7m)Please Note:RAMS: A work Method Statement and Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.
91	10 x Bays of Dexion boltless pallet racking Additional Information:comprising: 22 x end frames (7.5m), 48 x pairs various crossbeams (2.7m)Please Note:RAMS: A work Method Statement and Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.
92	3 x Bays of Dexion boltless pallet racking Additional Information:comprising: 4 x end frames (4.5m), 9 x pairs various crossbeams (2.7m)Please Note:RAMS: A work Method Statement and Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.
93	6 x Bays of Dexion boltless pallet racking Additional Information:comprising: 8 x end frames (7.5m), 43 x pairs various crossbeams (2.7m)Please Note:RAMS: A work Method Statement and Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.
94	10 x Bays of Dexion boltless pallet racking Additional Information:comprising: 11 x end frames (4.5m), 30 x pairs various crossbeams (2.7m)Please Note:RAMS: A work Method Statement and Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.
95	20 x Bays of Dexion boltless pallet racking Additional Information:comprising: 22 x end frames (7.5m), 80 x pairs various crossbeams (2.7m)Please Note:RAMS: A work Method Statement and Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.
96	20 x Bays of Dexion boltless pallet racking Additional Information:comprising: 22 x end frames (7.5m), 80 x pairs various crossbeams (2.7m)Please Note:RAMS: A work Method Statement and Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.
97	16 x Bays of Dexion boltless pallet racking Additional Information:comprising: 18 x end frames (7.5m), 96 x pairs various crossbeams (2.7m)Please Note:RAMS: A work Method Statement and Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.
98	20 x Bays of Dexion boltless pallet racking Additional Information:comprising: 22 x end frames (7.5m), 80 x pairs various crossbeams (2.7m)Please Note:RAMS: A work Method Statement and Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.
99	Dexion boltless pallet racking mezzanine floor Additional Information:comprising: 2 x 16 tread steel fabricated staircase, 75 x end frames (7.5m), 550 x pairs various crossbeams with Lodge Systems goods lift (550kg capacity)Please Note:LOLER: This lot has no record of Thorough Examination. The purchaser must ensure a Thorough Examination is carried out by a competent person prior to first use. The purchaser will be required to sign an undertaking confirming their agreement.RAMS: A work Method Statement and Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.
100	Approx. 5 pallets of kitchen components (Bay AD) Additional Information:see lot photos for additional details.Please Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Pallets will be removed to ground level prior to view day. Removal from site, including loading, remains the responsibility of the purchaser
102	Approx. 8 pallets of kitchen components (Bay AB) Additional Information:see lot photos for additional details.Please Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Pallets will be removed to ground level prior to view day. Removal from site, including loading, remains the responsibility of the purchaser
103	Approx. 9 pallets of kitchen components (Bay AA & Z) Additional Information:see lot photos for additional details.Please Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Pallets will be removed to ground level prior to view day. Removal from site, including loading, remains the responsibility of the purchaser
104	Approx. 7 pallets of kitchen components (Bay Y) Additional Information:see lot photos for additional details.Please Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Pallets will be removed to ground level prior to view day. Removal from site, including loading, remains the responsibility of the purchaser
105	Approx. 7 pallets of kitchen components (Bay X) Additional Information:see lot photos for additional details.Please Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Pallets will be removed to ground level prior to view day. Removal from site, including loading, remains the responsibility of the purchaser

214	Approx. 8 pallets of kitchen components (Bay CS) Additional Information:see lot photos for additional details.Please Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Pallets will be removed to ground level prior to view day. Removal from site, including loading, remains the responsibility of the purchaser
215	Approx. 6 pallets of kitchen components (Bay CT) Additional Information:see lot photos for additional details.Please Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Pallets will be removed to ground level prior to view day. Removal from site, including loading, remains the responsibility of the purchaser
216	Approx. 10 pallets of kitchen components (Bay CU) Additional Information:see lot photos for additional details.Please Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Pallets will be removed to ground level prior to view day. Removal from site, including loading, remains the responsibility of the purchaser
217	Approx. 9 pallets of kitchen components (Bay CX) Additional Information:see lot photos for additional details.Please Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.Pallets will be removed to ground level prior to view day. Removal from site, including loading, remains the responsibility of the purchaser
219	Qty of various kitchen components Additional Information:including end panels, kick boards, drawers and doors to 20 pallets
220	Qty of various kitchen components Additional Information:including framed doors, trims, wall panels etc to 6 pallets
250	Contents to 3 bays to include various sized door fronts and drawers (Row 0) Additional Information:see lot photos for additional details.Please Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.
251	Contents to 8 bays to include various sized door fronts and drawers (Row 1) Additional Information:see lot photos for additional details.Please Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.
252	Contents to 8 bays to include various sized door fronts and drawers (Row 2) Additional Information:see lot photos for additional details.Please Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.
253	Contents to 8 bays of door fronts, drawer fronts, frames and components (Row 3) Additional Information:see lot photos for additional details.Please Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.
254	Contents to 8 bays of door fronts, drawer fronts, frames and components (Row 4) Additional Information:see lot photos for additional details.Please Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.
255	Contents to 8 bays of door fronts, frames and side panels (Row 5) Additional Information:see lot photos for additional details.Please Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.
256	Contents to 8 bays of door and drawer fronts, side panels, frames etc (Row 6) Additional Information:see lot photos for additional details.Please Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.
257	Contents to 8 bays of door and drawer fronts, side panels, frames etc (Row 7) Additional Information:see lot photos for additional details.Please Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.
258	Contents to 8 bays of door and drawer fronts, side panels, frames etc (Row 8) Additional Information:see lot photos for additional details.Please Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.
267	Approx. 10 pallets of Kitchen & Bedroom components Additional Information:see lot photos for additional details.Please Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.
268	Approx. 10 pallets of Kitchen & Bedroom components Additional Information:see lot photos for additional details.Please Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.
274	Quantity of Work In Progress fitted furniture Additional Information:see lot photos for additional details.Please Note:RA: A Risk Assessment must be reviewed and approved by the Auctioneer prior to any removal work commencing on this lot.